COMPLETION REPORT

1. Name of Work : Providing CC Camera at Mantapa area and other area block spots in Mallasandra ward no 13 Shettyhalli sub division
2. Sanctioned Estimate No. & Dt : Rs. 7.50 lakhs
3. Amount as per tender : Rs.
4. Head of Account which is Chargeble : 3298
5. Work order No. Dt : 30/5/2020
6. Work Code : 33
7. Name of Contractor : GNANENDRA murthy. M.D
8. a.Time stipulated for completion of work :
   b.Dealy in execution of Work : M.B No. 4877
9. Measurement recorded in : Page No. 487651- 487661
10. Check Measurement of the Asst : Venkatachappa
    Asst. Exe. Eng./Exe.Eng : M.B. No. 4877
    Page No. 487651-487661
11. Name of the Office / Official Incharge of the work : Venkatachappa AE W.13
12. a.Asst. Engineer. : Venkatachappa AE.W.13
    b.Asst.Exe. Engineer : Nagesh Murthy. M. AEE

Sanctioned Estimate amount	Amount claims as per Actually vide as per bills	DIFFERENCE		
		Excess	Savings	Remarks
Rs. 7.50 Lacs	Rs. 715401.51	-	Rs.	

1. Certified that the above work has been completed within the stipulated time noted in the work order.
2. Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3. Certified that the above work has been executed by the contractor satisfactorily in accordance with the specification as embodied in the agreement.

Asst. Engineer

Asst. Executive Engineer
Shettyhalli Sub division
BBMP

EXECUTIVE ENGINEER
Bruhat Bengaluru Mahanagara Palike
Dasarahalli Division, Bengaluru-73.

Scanned by CamScanner